

Baylor 6032 Brake



Baylor 6032 Elmago Brake has been completely overhauled. All new coils and the brake has been subjected to Magnetic Particle inspection. All fits and tolerances have been checked and a complete data book from our third party brake rebuilder is included. Condition: Rebuilt.

Rating: Not Rated Yet

[Ask a question about this product](#)

Manufacturer [Baylor](#)